



SERVICE BULLETIN

Date: 07.08.09

Model: Elise/Exige '08 onwards

Number:
2009/04

CLASS 3

<i>Service Manager</i>	<i>Service Reception</i>	<i>Supervisor</i>	<i>Parts Manager</i>

TITLE: Erroneous ABS fault code.

REASON: Setting of CO232 fault code on ABS interrogation.

ACTION: When interrogating the ABS using the Lotus TechCentre on any 2008 model year onwards Elise or Exige, be aware that the ABS tell tale will be lit, and that code CO232 (Warning lamp short to ground) will be recorded. This is not an operational fault, and will not cause lamp illumination in service. This stored code, which cannot be cleared, should be disregarded.

sb_abs