



SERVICE BULLETIN

Date: 04.08.08

Model: Elise/Exige '08 M.Y.

Number:
2008/12

CLASS 2

Service Manager	Service Reception	Supervisor	Parts Manager

TITLE: Update of instrument pack calibration.

REASON: Improved tolerancing and CAN BUS filtering.
Ongoing development has resulted in an improved calibration for the 2008 M.Y. Elise/Exige instrument packs. Updating earlier cars will reduce the potential for frozen displays and enhance accuracy of displayed data.

ACTION: All dealers will be issued with a CD (T000T1501F) containing new instrument pack calibration for downloading to earlier '08 M.Y. Elise/Exige via the Lotus TechCentre.
Revised calibration has been installed on all Elise/Exige models from the following change point:

'08 M.Y. VIN serial number (last 4 digits of VIN); 0880

On all cars prior to the change point, carry out the following action:

At the next routine service, or earlier opportunity, perform an instrument pack Version Check as follows:

- Open the driver's door;
- Push in and hold the trip reset button on the column shroud;
- Still pressing the trip button, turn on the ignition (position 'II');
- Note the version number displayed at the top left hand side of the instrument pack LCD.
Early software is named VER.0.04 or VER.0.07
Latest software (supplied on CD) is named VER.0.08

Take no further action on any car with the latest software.

For other cars, follow the procedure detailed on the CD to download the latest software using the Lotus TechCentre.

CHARGES: For vehicles requiring updating, claims for 0.4 hr may be submitted quoting Operation Code 17.07.01 - 07, 'A' code 50, 'B' code 40. Please quote bulletin number in the text remarks section.

sb_IP calibration